



Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA,AD,..


Position

- 1 = A 962 086 XX
- 2 = B 960 457 XX
- 4 = A 961 798 NU
- 5 = A 963 667 NU
- 8 = A 962 096 NU
- 9 = A 962 097 XX
- 10 = A 961 338 NU
- 12 = A 960 486 NU
- 13 = A 963 305 NU
- 14 = A 962 098 XX
- 15 = A 961 182 NU (2x)
- 16 = A 960 219 NU
- 17 = A 960 342 NU




CERAPLUS
 A4160.. A4161..






0608 / A 865 821
 (+ A 865 612)
 Made in Germany



Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany



1
↓
13



	P bar			
		0,5	1	Q (3 bar)
	T °C			l/min
				9