







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

Position

- 1 = A 963 131 NU
- 4 = A 963 132 NU
- 8 = A 963 143 NU
- 9 = A 963 146 NU
- 10 = A 963 147 NU
- 14 = A 960 890 NU
- 16 = A 960 891 NU
- 17 = A 960 706 NU
- 18 = A 963 443 NU
- 20 = A 960 500 NU
- 21 = A 963 335 NU
- 22 = A 860 700 NU
- 23 = A 960 893 XX
- 24 = A 960 894 XX
- 25 = A 960 895 NU
- 26 = A 960 896 XX
- 27 = A 960 897 XX
- 28 = A 963 309 NU
- 29 = A 962 397 XX
- 30 = A 960 704 NU
- 31 = A 960 705 XX




XX = AA, AD...




MARA
A 9025 ..






1110 / A 866 106
(+ A 865 612)
Made in Germany






Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





0,3 MPa 3 bar	Thermometer icon	Snowflake icon	0	1	2	3	4	5	6	7	8	9
			°C	°C	°C	°C	°C	°C	°C	°C	°C	°C
	50°C	16°C	49,5	49,5	48	46	42,5	41	37	33,5	31	28
	65°C	16°C	65	65	63,5	60,5	57	53,5	49	44,5	39	34,5
	81°C	16°C	81	81	78,5	73	69	63,5	56	49	42,5	36



	P	bar		MAX. 10		5			Q
			0,5			1		(3 bar)	
	T	°C		MAX. 80		65			l/min
						55		25	