






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservdeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Резервју дају

- 1 A 963 131 NU
- 4 A 963 132 NU
- 8 A 963 143 NU
- 9 A 963 146 NU
- 10 A 963 147 NU
- 14 A 960 890 NU
- 16 A 960 891 NU
- 17 A 960 706 NU
- 18 A 963 443 NU
- 20 A 960 500 NU
- 21 A 963 335 NU
- 22 A 860 700 NU
- 23 A 960 893 XX
- 24 A 960 894 XX
- 25 A 960 895 NU
- 26 A 962 392 XX
- 27 A 960 562 XX
- 28 A 963 309 NU
- 29 B 960 473 XX
- 30 B 960 684 XX
- 31 A 960 704 NU
- A 962 476 NU
- 32 A 962 464 XX



XX = AA, AD...



CERAPLUS
 B 8654 ..






1110 / A 866 080
 (+ A 865 612)
 Made in Germany





Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





0,3 MPa 3 bar	50°C	16°C	0	1	2	3	4	5	6	7	8	9
			°C	°C	°C	°C	°C	°C	°C	°C	°C	°C
	65°C	16°C	49,5	49,5	48	46	42,5	41	37	33,5	31	28
	81°C	16°C	81	81	78,5	73	69	63,5	56	49	42,5	36



	P	bar		MAX. 10		5			Q	(3 bar)
	T	°C		MAX. 80		65 55			I/min	25

