






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservní deloví / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezerwju daju



XX = AA,AD

- 1 A 963 227 XX
- 2 A 963 054 NU
- 3 A 963 309 NU
- 4 A 963 817 XX
- 5 A 860 700 NU
- 6 A 963 335 NU
- 7 A 960 500 NU
- 10 A 963 707 NU
- 12 A 960 932 XX B9495
- A 963 708 XX B9612
- 13 A 963 706 XX
- 14 B 960 230 NU
- 16 A 960 470 NU
- 18 A 963 788 NU
- 21 A 962 143 NU
- 25 A 960 263 NU




CERAMIX BLUE
 B 9495 .. B 9612 ..




0511 / A 866 400
 (+ A 865 612)
 Made in Germany



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com





| Pressure 0,3 MPa 3 bar | Temperature °C | Symbol | 0 | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
|------------------------------|-------------------|--------|------|------|------|------|------|------|----|------|------|------|
| | | | °C | °C | °C | °C | °C | °C | °C | °C | °C | °C |
| | 50°C | 16°C | 49,5 | 49,5 | 48 | 46 | 42,5 | 41 | 37 | 33,5 | 31 | 28 |
| | 65°C | 16°C | 65 | 65 | 63,5 | 60,5 | 57 | 53,5 | 49 | 44,5 | 39 | 34,5 |
| | 81°C | 16°C | 81 | 81 | 78,5 | 73 | 69 | 63,5 | 56 | 49 | 42,5 | 36 |

| P | bar | MAX. 10 | 5 | Q (3 bar) |
|---|-----|---------|----|-----------------------|
| | | 0,5 | 1 | |
| T | °C | MAX. 80 | 65 | l/min |
| | | | 40 | B9495 11,5 B9612 8 |

