







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, AD...

Position


- 1 = E 960 641 XX
- 2 = A 961 885 XX
- 3 = A 961 886 XX
- 5 = A 962 998 NU
- 6 = A 961 889 NU
- 7 = A 962 229 NU
- 8 = A 962 230 NU
- 10 = A 961 640 NU (2x)
- 11 = A 963 823 XX
- 12 = A 961 891 XX
- 13 = A 963 033 NU
- 14 = A 963 432 NU
- 15 = A 860 780 XX
- 16 = A 960 394 XX
- 18 = A 962 594 NU (2x)
- 20 = A 961 810 NU (2x)
- 21 = A 961 892 NU
- 22 = A 960 599 XX
- 23 = A 960 601 XX
- 25 = A 963 838 XX
- 27 = A 961 810 NU
- 28 = A 963 651 NU
- 29 = A 961 893 XX
- 30 = A 961 894 XX




CERAPLUS




A 4088 .. A 4089 .. A 4093 .. A 4094 ..

1108 / A 865 706
 (+ A 865 612)
 Made in Germany



Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





	P	bar		MAX. 10		5		Q	(3 bar)
	T	°C		MAX. 80		65			l/min
						40			23

