




1




2








3



5




4



1

6

3



	<b>P</b>	bar				<b>Q</b> (3 bar)
	<b>T</b>	°C				<b>l/min</b>
						<b>13</b>








Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /  
 Rendelhető alkatrészek / Запасні частини / Reservní delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, AD,..






**Position**

- 1 = A 962 071 XX
- 2 = A 962 069 XX
- 3 = A 962 998 NU
- 4 = A 963 432 NU
- 5 = A 963 400 NU
- 7 = A 962 229 NU
- 8 = A 962 230 NU
- 9 = A 963 427 NU
- 10 = A 960 871 XX
- 13 = A 962 594 NU (2x)
- 14 = A 961 182 NU (2x)
- 16 = A 962 595 NU (2x)
- 17 = A 962 077 XX
- 18 = A 860 422 NU
- 19 = A 961 139 NU (2x)
- 21 = A 962 076 XX (2x)
- 22 = A 962 377 NU
- 23 = A 963 651 NU
- 24 = A 2401 XX
- 25 = T 2439 XX
- 26 = A 3306 XX



**MELANGE**  
 A 4279 .. A 4280 ..

0108 / A 865 810  
 (+ A 865 612)



Ideal Standard  
 Röntgenstrasse 9  
 54516 Wittlich  
 Germany

