







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daju



XX = AA, AD...




Position

1 = A 962 878 XX	19 = A 962 218 NU
4 = A 962 879 XX	20 = A 962 569 NU
5 = A 962 880 XX	21 = A 860 321 NU
6 = A 963 427 NU	24 = A 960 071 NU
7 = A 962 229 NU	25 = A 962 160 NU
10 = A 963 432 NU	27 = A 962 594 NU
11 = A 962 563 NU	29 = A 961 810 NU
13 = A 962 568 NU	30 = A 963 651 NU
15 = A 961 332 NU	31 = A 960 395 NU
16 = A 962 529 NU	A 960 196 NU
17 = A 962 857 NU	








**CERATHERM 200**  
**A 4630 ..**

0910 / A 866 278  
 (+ A 865 612)  
 Made in Germany



**Ideal Standard**  
 Roentgenstrasse 9  
 54516 Wittlich  
 Germany





P	bar	MAX. 10	5		Q (3 bar)
T	°C	MAX. 80	65 55		l/min 20,5

