






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu


XX = AA, AD...

Position


- 2 = A 860 200 AP
- 3 = A 960 201 XX
- 4 = A 860 601 NU
- 5 = A 860 602 XX
- 6 = A 961 268 NU
- 8 = A 961 210 NU
- 9 = A 960 017 NU
- 11 = A 962 105 NU
- 13 = A 860 607 NU
- 15 = A 960 005 XX
- 16 = A 960 092 NU
- 20 = A 960 093 NU
- 21 = A 960 016 NU
- 22 = A 963 600 NU
- 23 = A 961 172 NU
- 24 = A 961 230 XX
- 29 = A 860 615 NU



A5334
831801000



A5333
831301000




JADO


0907 / A 865 170
 (+ A 865 613)
 Made in Germany

GLANCE


A 5330 .. A 5331 .. A 5333 .. A 5334 ..
 A 5413 .. H 3522 .. H 3524 ..

















A5331
831901000



A5330
831001000





| | | | | | | |
|--|----------|-----|--|--|--|---------------------|
| | P | bar | | | | Q (3 bar) |
| | T | °C | | | | l/min 8 |