







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservdeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, GN, ...

Pos.	Part No.
1	A 963 131 NU
2	A 963 132 NU
3	A 963 146 NU
4	A 960 890 NU
5	A 962 594 NU
6	A 860 904 NU
7	A 960 891 NU
8	A 960 898 NU
9	A 960 899 NU
10	A 963 564 NU
11	A 963 427 NU
12	A 962 391 XX
13	A 860 906 XX
14	A 860 897 NU

15	A 861 409 XX
16	A 961 659 NU
17	A 962 388 XX
18	F 960 952 XX
19	A 960 704 NU
	A 962 476 NU
20	A 6677 XX





Ideal Standard

CERATHERM T100


A 5813 ..












0121 / A 868 857
 Made in Germany



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





	P	bar		MAX. 10		5		Q	(3 bar)
	T	$^{\circ}\text{C}$		MAX. 80		65		l/min	30