







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /  
 Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, GN, ...

Pos.	Part No.
1	A 861 405 XX
2	A 963 309 NU
3	A 861 406 NU
4	B 961 373 XX
5	B 961 374 NU
6	A 861 181 NU
7	A 861 156 NU
9	A 960 183 NU
10	F 961 122 NU
11	A 962 359 NU
13	E 960 059 NU
15	B 961 383 XX
17	A 964 520 NU
18	B 960 900 XX
19	A 961 172 NU
20	A 961 230 XX



P	T	°C	0	1	2	3	4	5
			°C	°C	°C	°C	°C	°C
0,3 MPa 3 bar	50°C	15°C	50	49	44	40	35	33
	65°C	15°C	65	63	57	50	44	40
	85°C	15°C	85	83	74	64	56	50




Ideal Standard

## CONNECT AIR


A 7021 .. A 7024 .. A 7053 .. A 7055 ..







0420 / A 868 383  
 (+ A 865 612)  
 Made in Germany



Ideal Standard International NV  
 Corporate Village - Gent Building  
 Da Vincilaan 2  
 1935 Zaventem  
 Belgium

www.idealstandardinternational.com





	<b>P</b>	<b>bar</b>	0,5		<b>MAX. 10</b>	5		<b>Q</b> (3 bar)
	<b>T</b>	<b>°C</b>			<b>MAX. 85</b>	65		<b>l/min</b>
						40		<b>5</b>